	oane						RADIOI			Y FORM	
CONTRAC	T NO / TO N 10-D-0808	NO: N62473-	PROJECT TITLE / LOCATION: Rad Remediation D-1, Phase II / HPNS					ITSI GILBANE PROJECT NO: 07204.0004			
Survey No.:	07204.0004		Date: 7/23/2014			Location: HPNS		vs	Survey Type: Information		
Chris Robbins			Cruidophe J Rollini			Ed Palser			50-		
Те	ch Printed N	ame	Signature			RSO Printed Name			Signature		
		Cal Due	Probe	Probe	Instrur Cal Due	nent(s) BKG	BKG	BKG	BKG	Ecc	TOCC
Model	Serial	Date	Model	Serial	Date	α	β	βKG γ.	μr/Hr	Eff. α	Eff. β
19	286213	7/27/2014	N/A					>	5.4	N/A	
N/A	TERRITE SECTION	PERSONAL PROPERTY AND INC.		A STATE OF THE STATE OF			DANS SERVICE STREET	EUN STATISTICAL CONTROL			
N/A				Ciner	ey Descripti	on / Mon /I	Photo				
	<del></del>			Surv	ey Descripti	ion / iviap /i	11010				
Survey Ui Trench #:	nit	K 04-PDT-0	11								
Soil Survey Units			D0025	N/A			N/A				
			N/A			<del>&gt;</del>	N/A				
(D0001 to	D0042)							•			
From the 1	Bottom of	Trench					μR/Hr	μR/Hr	μR/Hr	μR/Hr	
Soil Compaction Lift From			0	ft to	1	1	7	7 7	6	7 7	
Soil Compaction Lift From			1	ft to	2		6	7	6	6	
Soil Compaction Lift From			2	ft to	3		6	6	6	5	
_	Soil Compaction Lift From			ft to	4		N/A	N/A	N/A	N/A	
Soil Compaction Lift From Soil Compaction Lift From			5	ft to	5						
Soil Compaction Lift From			6	ft to ft to	6 7						
Soil Compaction Lift From			7	ft to	8						
Soil Compaction Lift From			8	ft to	9						
Soil Compaction Lift From			9	ft to	10				٠		
Soil Comp	action Lift	From	10	ft to	11						
									4		
Comments	: Informat	ional Surve	y During	Backfill O	peration. D	ose rates t	aken at 1 n	neter above	e surface t	o support	
					instrument						
					•						

Page 1 of 2

